

Table of Contents

AutoCAD 2004 3D Drawing & Modeling

Module 1: Basic 3D Concepts

Section 1: Foundations

- Why Use 3D?
- Types of 3D Models
- Wireframe Modeling
- Surface Modeling
- Solid Modeling
- Basic Viewing in 3D
- Rotating the View
- Adding Thickness to 2D Objects
- Setting the Elevation
- Using Multiple Viewports
- Command Summary
- Self Check: Foundations

Section 2: Working with 3D Coordinates

- AutoCAD's 3D Coordinate System
- Using Object Snaps in 3D
- Point Filters
- Introduction to the User Coordinate System
- Moving the UCS Origin
- The UCS View Option
- The UCS 3 Point Option
- Working with Multiple UCSs
- Command Summary
- Self Check: Working with 3D Coordinates
- Project Exercise: Basic 3D Concepts

Module 2: Creating Surfaces

Section 1: Simple Surface Objects

- Creating Flat 3D Surfaces
- 3D Surface Primitives
- Command Summary
- Self Check: Simple Surface Objects

Section 2: Complex Surfaces

- Creating More Complex Surfaces
- Extruded (Tabulated) Surface
- Revolved Surface
- Creating Surfaces from Edges
- Creating Ruled Surfaces
- Editing 3D Surfaces

- Command Summary
- Self Check: Complex Surfaces
- Project Exercises: Creating Surfaces

Module 3: Solid Modeling

- Section 1: Simple Solids
 - Solid Modeling
 - Creating Boxes and Wedges
 - Creating Cylinders and Cones
 - Creating Spheres and Tori
 - Command Summary
 - Self Check: Simple Solids
- Section 2: Creating Composite Solids
 - Boolean Operations
 - Joining Solids
 - Subtracting Solids
 - Finding the Common Volume
 - Interference Checking
 - Command Summary
 - Self Check: Creating Composite Solids
- Section 3: Creating Solids from 2D Objects
 - Swept Solids
 - Extruded Solids
 - Revolved Solids
 - The UCS Face Option
 - Command Summary
 - Self Check: Creating Solids from 2D Objects
- Project Exercises: Solid Modeling

Module 4: Editing Solids

- Section 1: Adding Features to Solids
 - Creating 3D Fillets
 - Creating 3D Chamfers
 - Slicing a Solid along a Plane
 - Cross-Sectional Views
 - Command Summary
 - Self Check: Adding Features to Solids
- Section 2: Advanced Solids Editing
 - Using the SOLIDEDIT Command
 - Extruding and Offsetting Faces
 - Moving and Rotating Faces
 - Tapering a Face
 - Creating a Shell
 - Removing Faces
 - Imprinting and Cleaning
 - Additional Options
 - Command Summary
 - Self Check: Advanced Solids Editing

Project Exercises: Editing Solids

Module 5: Manipulating 3D Objects

Section 1: Advanced UCS Options

- Tracking the Screen
- The UCS X, Y, and Z Options
- Saving a UCS by Name
- OrthoGraphic UCSs
- Named Views in 3D
- Command Summary
- Self Check: Advanced UCS Options

Section 2: Editing in 3D

- Aligning Objects in 3D
- Mirroring Objects in 3D
- Rotating Objects in 3D
- Arraying Objects in 3D
- Getting Information about 3D Objects
- Command Summary
- Self Check: Editing in 3D
- Project Exercise: Manipulating 3D Objects

Module 6: Working Drawings and 3D Objects

Section 1: Working with Layouts

- Layouts: A Review
- Creating and Scaling Viewports
- Controlling Viewport Display
- Special Floating Viewports Setup
- Command Summary
- Self Check: Working with Layouts

Section 2: 2D Drawings from 3D Models

- 2D Views from 3D Solids
- Creating Hidden Line Views
- Creating Profiles from Solids
- Inserting Rendered Images
- Dimensioning in Layouts
- Command Summary
- Self Check: 2D Drawings from 3D Models
- Project Exercises: Working Drawings and 3D

Module 7: Presenting the 3D Model

Section 1: Refining the View

- Perspective Views
- Working with Camera and Target
- Clip Planes
- Command Summary
- Self Check: Refining the View

Section 2: Rendering

Rendering Concepts
Attaching Materials to the Model
Scenes and Lighting
Adding Extras
Command Summary
Self Check: Rendering
Project Exercise: Presenting the 3D Model

Module 8: Additional Drawing Projects

Wireframe Mount
Rod Guide Working Drawing
Architectural Massing Study

Skills Assessment